

Please read this guide before installation

iGAGING EZ Depth DRO can be mounted to a variety of drill presses in 4 different methods:

Method 1 & 2:

For drill press with plastic collar depth rod or without depth rod, please remove the plastic collar (Fig.1 & 2).

Mount the supplied collar clamp and quill bracket to the drill press collar (Fig.3)

Mount the DRO unit (Fig.4)

Method 3 & 4 (for heavy duty drill press):

For drill press with *Stop Bracket*, (Fig.5 & 6) and for drill press with *Offset Bracket* (Fig.7 & 8) directly mount to the Depth Stop Rod. (Fig.9) shows the rear view of DRO unit mounting.

For Method 1 & 2




Fig.1

Drill Press with or without the plastic collar




Fig.2

Remove the plastic collar




Fig.3

Mounting the Display Bracket, Quill Brackets with Collar Clamp




Fig.4

Tighten the Locking Screw for the Collar Clamp

For Method 3 & 4




Fig.5

Depth Stop Rod mounting




Fig.6

DRO unit mounting to the Stop Bracket




Fig.7

Offset Bracket mounting




Fig.8

DRO unit mounting to the Offset Bracket




Fig.9

Rear view of DRO unit mounting