


6 & 12" DIGITAL HEIGHT GAUGE - ABSOLUTE

1. Gauge Base (magnetic base for the 35-629)
2. Measuring scribe
3. Battery Compartment
4. Main Carriage with LCD display
5. Column
6. Fine Adjustment Carriage
7. Fine Adjustment Nut
8. Fine Adjustment Carriage
9. Main Carriage Lock
10. Function keys



Product detail

- Large easy to read LCD display
- Absolute Technology which memorize origin zero
- Range: #35-629 0-6"/0-150mm | #35-630 0-12"/0-300mm
- Resolution: 0.0005"/0.01mm
- Accuracy: 0.001"/6" | 0.002"/12"
- Indication variability: 0.0005"/0.01mm
- SPC/USB data port (#35-630-USB for data output kit)
- Carbide tipped scribe
- ABS/INC measurement
- Auto-Power-Off
- Battery: 3V CR2032, one piece. Display not turning on or flashing indicate new battery is needed.

Function keys:

- ON/OFF: turn unit on or off
- mm/in key: switch between inch / metric
- ABS/INC: Absolute/incremental measure. Press the key, screen will display 0.00 and INC (incremental)
Press the key again, to disable the feature.
- Hold: hold display reading
- Origin: Absolute Origin, Self memorizes and recognizes origin zero.
Press key for 3 seconds to set origin zero.

Care:

- Keep the tool clean and dry.
- Avoid shocks or impacts.
- Avoid strong magnetic fields.
- Use with care.